



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

*IPW* *b/cote*  
PATENT

In re Patent of:

TOSHIO SUZUKI

Appln. No.: 10/079,898

Filed: February 22, 2002

For: METHOD FOR PRODUCING INK JET  
RECORDING HEAD, AND INK JET  
RECORDING HEAD PRODUCED  
BY SUCH METHOD

U.S. Patent No.: US 6,811,715 B2

Issued: November 2, 2004

)  
: Examiner: Anita Alanko  
)  
: Group Art Unit: 1765  
)  
:  
)  
:  
)  
:  
)  
:  
)  
:  
)  
:  
)  
:  
)  
:  
)

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

04/06/2005 MBIZUNES 00000090 6811715

01 FC:1811

100.00 OP

CERTIFICATE OF CORRECTION  
UNDER RULES 322 AND 323


Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentee's undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



John A. Krause  
Attorney for Patentee  
Registration No. 24,613

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
Facsimile: (212) 218-2200  
NY\_Main 492063v1

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : US 6,811,715 B2

DATED : November 2, 2004

INVENTOR(S) : TOSHIO SUZUKI

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 2:

Line 8, "hydroclophilizing" should read --hydrophilizing--;

Line 12, "is" should read --has--; and

Line 13, "hyrdophilicity" should read --hydrophilicity--.

COLUMN 7:

Line 31, "mJ/cm" should read --mJ/cm<sup>2</sup>--.

COLUMN 8:


Line 7, "is remained" should read --remains--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,811,715 B2

No. of add'l. copies  
@ 30¢ per page



STAPLE  
HERE  
ONLY

PRINTER'S TRIM LINE

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : US 6,811,715 B2

DATED : November 2, 2004

INVENTOR(S) : TOSHIO SUZUKI

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 10:

Line 7, "Al203," should read --Al<sub>2</sub>O<sub>3</sub>--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. US 6,811,715 B2

No. of add'l. copies  
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

NY\_Main 492063v1

